

[Print](#)

Project Name: KLAL RNAV GPS RWY 23

Project Reason: Added chart note: VGSI and RNAV glidepath not coincident (VGSI Angle {angle}/TCH {feet}) due to updated VGSI data in AIRNAV and addition of raised LNAV/VNAV minimums from temporary NOTAM.

Last Updated By: Casey Hill

Last Updated At: 2022-02-16 20:04:26.031702

Status: Verified

2/8521

!FDC X/XXXX LAL IAP LAKELAND LINDER INTL, LAKELAND, FL. RNAV (GPS) RWY 23, ORIG-F... CHART PROFILE
NOTE: VGSI AND RNAV GLIDEPATH NOT COINCIDENT (3.00/46.1). LNAV/VNAV DA 522/HAT 381 ALL CATS. THIS IS
RNAV (GPS) RWY 23, ORIG-G. 2202162004-PERM

Digitally signed by
DAVID TEFFETELLER
Feb 28, 2022

