

Flight Procedures Cover Page	Task Action: P-NOTAM	Task Type: IAP	Estimated Chart Date: 07/15/2021	APWS Task ID: A25F2FE7C39047EE891AC808B8DA9334	APWS Project ID: C95C1E8BBB1A407E9B4FBDB8FE210A05
Procedure: RNAV (GPS) RWY 9 AMDT 0A		Enroute: NO	Specialist: Moore, Frank		Agreement Number:
Airport ID: C91			Airport City: DOWAGIAC		State: MI
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
<p>Procedure Comments:  P-NOTAM 1/8248  This Cancels FDC 0/8793  Order 8260.3, chapter 2, New Circling Criteria Applied.    CONTACT DAVE TEFFETELLER 202-267-5177.</p>					

QUALITY  
45  
CHECKED

QUALITY  
15  
CHECKED

APP CRS	Rwy Idg	4700
095°	TDZE	740
	Apt Elev	747

RNAV (GPS) RWY 9

DOWAGIAC MUNI (C91)

<div> <div>▼</div> <div>▲ NA</div> </div> <p>DME/DME RNP-0.3 NA. Procedure NA at night.          Visibility reduction by helicopters NA. Obtain local altimeter setting on CTAF, when not received, use Elkhart altimeter setting and increase all MDA 60 feet; increase LNAV and Circling Cat C visibility ¼ mile.</p>	<p>MISSED APPROACH: Climb to 2700 direct YEGTU and hold.</p>
---	--

<p>SOUTH BEND APP CON ★</p> <p>118.55 257.8</p>	<p>UNICOM</p> <p>122.8 (CTAF) 0</p>
---	-------------------------------------





