

Flight Procedures Cover Page	Task Action: P-NOTAM	Task Type: IAP	Estimated Chart Date: 10/07/2021	APWS Task ID: A2D13DA105C64D288F6A90FE408EFEDC	APWS Project ID: B73C2970248945DFBA9467DB5E8ACF15
Procedure: RNAV (GPS) RWY 3 AMDT 0B		Enroute: NO	Specialist: Hanby, William		Agreement Number:
Airport ID: 43A			Airport City: STAR		State: NC
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
<p>Procedure Comments: PROCESSED IAW AIRCRAFT OPERATIONS GROUP (AJF-1000) MEMO, DATED JUNE 4, 2020, SUBJECT: FLIGHT INSPECTION OF NEW CONTROLLING OBSTACLES.</p> <p>New Final Stepdown Fix Controlling Obstacle: Changed from LP and LNAV 749 TREE 352140N/0794811W to LP 713 Transmission Line (37-149723) 352154N/0794744W and LNAV 742 Water Tower (37-149364) 352131N/0794721W - new obstacle survey.</p> <p>Pending Data utilized.</p> <p>Contact Manager John Bordy, IFP Team 2, Sub-Team B, AJV-A422 at: (405) 954-0980.</p>					








