



Flight Procedures Cover Page	Task Action: P-NOTAM	Task Type: IAP	Estimated Chart Date: 08/12/2021	APWS Task ID: ADB7206576DE46F09B720D58D9415B26	APWS Project ID: 45318A5CA7D346C3B15A6C76C49B9CAB
Procedure: ILS OR LOC RWY 5 AMDT 0C		Enroute: NO	Specialist: Boone-walt, Rose		Agreement Number:
Airport ID: KCAK			Airport City: AKRON		State: OH
Facility ID: EQX	Facility Type: ILS	Flight Inspection Remark Type:			
<p>Procedure Comments: P-NOTAM</p> <p>CIRCLING RADII INCREASE</p> <p>CONTACT JASON KRETSCHMER, AJV-A421, 405-954-4019</p> <div style="display: flex; justify-content: space-between; align-items: center;"> <div style="text-align: center;"> <p><i>Digitally signed by</i> JASON KRETSCHMER Jun 10, 2021</p> </div> <div style="text-align: center;">  </div> </div> <div style="text-align: right; margin-top: 500px;">  </div>					

LOC/DME I-EQX 108.3 Chan 20	APP CRS 054°	Rwy Idg TDZE Apt Elev 8204 1199 1228
---	------------------------	--

OLD

ILS or LOC RWY 5
AKRON-CANTON RGNL (CAK)

▽ **RVR 1800 authorized with use of FD or AP or HUD to DA.	MALSR 	MISSED APPROACH: Climb to 2000 then climbing left turn to 3000 direct ACO VOR/DME and hold.
--	-----------	---

ATIS 121.05	CLEVELAND APP CON * 125.5 269.25	AKRON-CANTON TOWER 134.75 279.575	GND CON 121.7 348.6	CLNC DEL 132.05
-----------------------	--	---	-------------------------------	---------------------------

