

Flight Procedures Cover Page	Task Action: Amendment	Task Type: FIX	Estimated Chart Date: 12/29/2022	APWS Task ID: B9EE3769BCF74DA9BDD0C4E6D09802A5	APWS Project ID: DBC11027FDC644719A2651A16443A516
Procedure: FIX HOLLY SPRINGS VORTAC 21 MS US		Enroute: NO	Specialist: Teffeteller, David		Agreement Number:
Airport ID:			Airport City:		State:
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
<p>Procedure Comments:</p> <p>FC REQUEST TO REMOVE V54 FROM FIX USE</p> <p>CONTACT DAVE TEFFETELLER/240-457-1998</p>					

