

TRANSMITTAL OF AIRWAYS/ROUTES DATA

AIRWAY NO or ROUTE

V139

ROUTINE or DOCKET NO

<u>FROM</u>	<u>STATE</u>	<u>FB/FO</u>	<u>TO</u>	<u>STATE</u>	<u>FB/FO</u>	<u>RNP</u>	<u>LEG TYPE</u>
HAMPTON (HTO) VORTAC	NY		TRAIT	RI			
<u>OBSTRUCTION</u>	<u>COORDINATES</u>		<u>ELEV MSL</u>	<u>CONT OBS</u>	<u>AC</u>	<u>ROC</u>	<u>ADJUSTMENTS</u>

<u>MRA</u>	<u>MOCA</u>	<u>PUB</u>	<u>MAA</u>	<u>D/D/I</u>	<u>MEA (1)</u>	<u>DIRECTION (1)</u>	<u>MEA (2)</u>	<u>DIRECTION (2)</u>	<u>GNSS MEA</u>
------------	-------------	------------	------------	--------------	----------------	----------------------	----------------	----------------------	-----------------

<u>COP</u>	<u>FIX MRA</u>	<u>FIX MCA</u>	<u>MTA</u>
------------	----------------	----------------	------------

SEGMENT REMARKS

SEGMENT UNUSABLE

CHANGES-REASON

SEGMENT SPLIT AT TRAIT - HTO VORTAC UNUSABLE ON R-052.

TRANSMITTAL OF AIRWAYS/ROUTES DATA

AIRWAY NO or ROUTE

V139

ROUTINE or DOCKET NO

<u>FROM</u>	<u>STATE</u>	<u>FB/FO</u>	<u>TO</u>	<u>STATE</u>	<u>FB/FO</u>	<u>RNP</u>	<u>LEG TYPE</u>
TRAIT	RI		PROVIDENCE (PVD) VOR/DME	RI			TF

<u>OBSTRUCTION</u>	<u>COORDINATES</u>	<u>ELEV MSL</u>	<u>CONT OBS</u>	<u>AC</u>	<u>ROC</u>	<u>ADJUSTMENTS</u>
--------------------	--------------------	-----------------	-----------------	-----------	------------	--------------------

TOWER (44-000122)	412941.77N/0714704.70W	1049		4D	1000	
-------------------	------------------------	------	--	----	------	--

TERRAIN	413521.00N/0713912.00W	613	Y
---------	------------------------	-----	---

<u>MRA</u>	<u>MOCA</u>	<u>PUB</u>	<u>MAA</u>	<u>D/D/I</u>	<u>MEA (1)</u>	<u>DIRECTION (1)</u>	<u>MEA (2)</u>	<u>DIRECTION (2)</u>	<u>GNSS MEA</u>
------------	-------------	------------	------------	--------------	----------------	----------------------	----------------	----------------------	-----------------

3000	2100	Y	17500		3000				
------	------	---	-------	--	------	--	--	--	--

<u>COP</u>	<u>FIX MRA</u>	<u>FIX MCA</u>	<u>MTA</u>
------------	----------------	----------------	------------

HTO 28 NM

SEGMENT REMARKS

AIRSPACE FLOOR (1200) AND BUFFER (500) USED TO EVALUATE AIRSPACE.

CHANGES-REASON

SEGMENT SPLIT DUE TO HTO VORTAC UNUSABLE ON R-052.

COP ADDED AT TRAIT - HTO UNUSABLE ON R-052.

MRA/MEA CHANGED FROM 2000 TO 3000 - RESTICTION: PVD VOR/DME UNUSABLE 106-294 BYD 30NM BELOW 3000; VOR 4/22/2016.

CHANGED MOCA FROM 1700 TO 2100 AND PUB CHANGED FROM NO TO YES - NEW CONTROLLING OBSTRUCTION/MEA RAISED TO 3000.

<u>FLIGHT CHECK</u>	<u>DATE</u>	<u>OFFICE</u>	<u>NAME</u>
---------------------	-------------	---------------	-------------

PROCESSED IAW AIRCRAFT OPERATIONS GROUP (AJW-33) MEMO, OCT 3, 2018, SUBJECT: FLIGHT INSPECTION REVIEW NOT REQUIRED.

<u>APPROVED</u>	<u>DATE</u>	<u>OFFICE</u>	<u>TITLE</u>	<u>NAME</u>
-----------------	-------------	---------------	--------------	-------------

		AJV-A430	MANAGER	GEORGE DAVIS
--	--	----------	---------	--------------

Digitally signed by

DONALD H LANIER

May 11, 2020

Digitally signed by

DONALD H LANIER

May 11, 2020