

|   |                         |                                |                                     |   |  |
|---|-------------------------|--------------------------------|-------------------------------------|---|--|
| Flight Procedures Cover Page  | Task Action:<br>P-NOTAM | Task Type:<br>IAP              | Estimated Chart Date:<br>04/22/2021 | APWS Task ID:<br>E102EB917D8649298144DEBED04E52F1 | APWS Project ID:<br>29ACF425BB154131B875F921769A09D7 |
| Procedure:<br>ILS OR LOC RWY 22L AMDT 13E   |                         | Enroute:<br>NO                 | Specialist:<br>Hanby, William       |   | Agreement Number:                                    |
| Airport ID:<br>KEWR   |                         | Airport City:<br>NEWARK        |                                     | State:<br>NJ                                      |  |
| Facility ID:  | Facility Type:          | Flight Inspection Remark Type: |                                     |   |  |
| <p><b>Procedure Comments:</b><br/>P-NOTAM: DELETE INNER MARKERS EZA AND LSQ FROM ILS OR LOC RWY 4R/22L 4/22/2021 DECOMMISSIONING.</p> <p>Processed IAW Aircraft Operations Group (AJF-10) Memo, April 29, 2020<br/>Subject: Flight Inspection Review Not Required.</p> <p>CONTACT MR. JOHN BORDY, IFP Team 2, Sub-Team B, AJV-A422 AT 405-954-0980.</p> |                         |                                |                                     |   |  |

Digitally signed by **MARY MCDONALD** 12  
Jan 11, 2021

QUALITY  
8  
CHECKED