

TRANSMITTAL OF AIRWAYS/ROUTES DATA

AIRWAY NO or ROUTE

V473

ROUTINE or DOCKET NO

<u>FROM</u>	<u>STATE</u>	<u>FB/FO</u>	<u>TO</u>	<u>STATE</u>	<u>FB/FO</u>	<u>RNP</u>	<u>LEG TYPE</u>
LEVEL ISLAND (LVD) VDME	AK		FLIPS	AK			

<u>OBSTRUCTION</u>	<u>COORDINATES</u>	<u>ELEV MSL</u>	<u>CONT OBS</u>	<u>AC</u>	<u>ROC</u>	<u>ADJUSTMENTS</u>
AAO	563803.00N/1344536.00W	3449		4E	2000	
TERRAIN	563351.00N/1345142.00W	3874	Y			

<u>MRA</u>	<u>MOCA</u>	<u>PUB</u>	<u>MAA</u>	<u>D/D/I</u>	<u>MEA (1)</u>	<u>DIRECTION (1)</u>	<u>MEA (2)</u>	<u>DIRECTION (2)</u>	<u>GNSS MEA</u>
9000	6300	Y	17500		9000				

<u>COP</u>	<u>FIX MRA</u>	<u>FIX MCA</u>	<u>MTA</u>
DL FLIPS		FLIPS 9000E	

SEGMENT REMARKS

RETAINED MOCA.
AIRSPACE FLOOR (1200) AND BUFFER (500) USED TO EVALUATE AIRSPACE.

CHANGES-REASON

MEA(1): CHANGED MEA(1) FROM 7000 TO 9000 PER FLIGHT CHECK REPORT MAY 2020
FIX MCA: ADDED MCA 9000 FLIPS EASTBOUND PER FLIGHT CHECK REPORT MAY 2020
MRA: CHANGED MRA FROM 7000 TO 9000 PER FLIGHT CHECK REPORT MAY 2020

<u>FLIGHT CHECK</u>	<u>DATE</u>	<u>OFFICE</u>	<u>NAME</u>
---------------------	-------------	---------------	-------------

PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021, SUBJECT: GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION.

<u>APPROVED</u>	<u>DATE</u>	<u>OFFICE</u>	<u>TITLE</u>	<u>NAME</u>	<u>Digitally signed by</u>
		AJV-A431	MANAGER	JOHNNIE BAKER	DAVID TEFFETELLER
					Aug 18, 2022

Digitally signed by

DAVID TEFFETELLER

Aug 18, 2022