


Flight Procedures Cover Page	Task Action: Amendment	Task Type: FIX	Estimated Chart Date: 01/27/2022	APWS Task ID: F199B5107E524A009A64D6D1ABC80950	APWS Project ID: DBFF91DAF1204ACAB358E03E8B0CD5C8
Procedure: FIX HURCN 1 FL US		Enroute: NO	Specialist: Byrns, Tommy		Agreement Number:
Airport ID:			Airport City:		State:
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
<p>Procedure Comments: MULTIPLE FIXES: HURCN JAYMC KPASA SMELZ</p> <p>PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021, SUBJECT: GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALDIATION.</p> <p>CONTACT ALLAN WILL, 405-954-6103.</p> <p style="text-align: center;"><i>Digitally signed by</i> JASON KRETSCHMER Dec 16, 2021</p> <p style="text-align: right;">12/16/2021</p> <p style="text-align: right;">  </p>					