

PREPARED BY THE PRODUCT SUPPORT GROUP, AJV 34

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

| AIRAC DATE | STATE | CITY | AIRPORT | FDC NUMBER | FDC DATE | SUBJECT |
|---------------|-------|------------------|--------------|---------------|-------------|-------------------------------|
| 18-Sep-14 | CT | Windsor Locks | Bradley Intl | 4/4246 | 08/08/14 | ILS OR LOC RWY 33, Amdt 10 |

AIRAC Date: 18 SEP 2014

FDC **4/4246** BDL IAP BRADLEY INTL, WINDSOR LOCKS, CT. ILS OR LOC RWY 33, AMDT 10... S-ILS 33: DA 371. S-LOC 33: HAT 389 ALL CATS. CHART TDZE 171 DELETE THRE 168. THIS IS ILS OR LOC RWY 33, AMDT 10A. 1404161416-PERM