

**PREPARED BY THE PRODUCT SUPPORT GROUP, AJV 34**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:  
.....EFFECTIVE UPON PUBLICATION

| AIRAC<br>DATE | STATE | CITY      | AIRPORT        | FDC<br>NUMBER | FDC<br>DATE | SUBJECT            |
|---------------|-------|-----------|----------------|---------------|-------------|--------------------|
| 11-Dec-14     | WA    | Arlington | Arlington Muni | 4/9882        | 10/14/14    | LOC RWY 34, Amdt 5 |

**AIRAC Date: 11 DECEMBER 2014**

**FDC 4/9882** AWO IAP ARLINGTON MUNI, ARLINGTON, WA. LOC RWY 34, AMDT 5...  
S-34 HAT 445 ALL CATS. CHART TDZE 135 DELETE THRE 128. THIS IS LOC RWY  
34, AMDT 5A. 1409251937-PERM