

U.S. Department  
of Transportation

800 Independence Ave., S.W  
Washington, D.C. 20591

**Federal Aviation  
Administration**

**Transmittal Letter 15-02**

**December 5, 2015**

**PREPARED BY THE PRODUCT SUPPORT GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows: .....EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
8-Jan-15	TN	Tullahoma	Tullahoma Rgnl Arpt/Wm Norhtern Field	4/2912	11/21/15	VOR RWY 24, Orig-C

**AIRAC Date: 8 JANUARY 2015**

FDC **4/2912** THA IAP TULLAHOMA RGNL ARPT/WM NORTHERN FIELD, TULLAHOMA, TN. VOR RWY 24, ORIG-C... DELETE NOTE: WHEN VGSI INOPERATIVE, PROCEDURE NA AT NIGHT.

THIS IS **VOR RWY 24, ORIG-D.**