

U.S. Department  
of Transportation

800 Independence Ave., S.W  
Washington, D.C. 20591

**Federal Aviation  
Administration**

**Transmittal Letter 15-08**

**February 27, 2015**

**PREPARED BY THE PRODUCT SUPPORT GROUP, AJV-34  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows: .....EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
2-Apr-15	TX	Midland	Midland Intl	5/7067	02/11/15	RNAV (GPS) RWY 28, Amdt 2

**FDC 5/7067** MAF IAP MIDLAND INTL, MIDLAND, TX. RNAV (GPS) RWY 28, AMDT 2... LPV DA 3058. LNAV/VNAV DA 3137. LNAV HAT 422 ALL CATS. CHART TDZE 2858 DELETE THRE 2855.

**THIS IS RNAV (GPS) RWY 28, AMDT 2A. 1501271500-PERM**