

U.S. Department
of Transportation

800 Independence Ave., S.W.
Washington, D.C. 20591

**Federal Aviation
Administration**

Transmittal Letter 15-17

July 2, 2015

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME,
LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

| AIRAC DATE | STATE | CITY | AIRPORT | FDC NUMBER | FDC DATE | SUBJECT |
|---------------|-------|-------|------------------------------|---------------|-------------|---|
| 20-Aug-15 | FL | Miami | Kendall-Tamiami Executive | 5/4465 | 06/29/15 | Takeoff Minimums and (Obstacle) DP, Amdt 8 |

EFFECTIVE 20 AUGUST 2015

**FDC 5/4465 TMB ODP KENDALL-TAMIAMI EXECUTIVE, MIAMI, FL. TAKEOFF
MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES AMDT 8...
CHANGE AIRPORT NAME TO READ: MIAMI EXECUTIVE. THIS IS TAKEOFF
MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES, AMDT 8A.
1506251220-PERM**