

**Federal Aviation  
Administration**

**Transmittal Letter 20-23**

**September 18, 2020**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,  
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,  
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:  
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
11/5/2020	AK	St Mary's	St Mary's	0/6454	8/28/2020	LOC/DME RWY 17, Amdt 5C

**AIRAC Date: 5 NOVEMBER 2020**

FDC 0/6454 KSM IAP ST MARY'S, ST MARY'S, AK. LOC/DME RWY 17, AMDT 5C...  
CHART CIRCLING ICON. THIS IS LOC/DME RWY 17, AMDT 5D. 2007301216-PERM