

U.S. Department  
of Transportation

800 Independence Ave., S.W.  
Washington, D.C. 20591

**Federal Aviation  
Administration**

**Transmittal Letter 15-17**

**July 2, 2015**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME,  
LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,  
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:  
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
20-Aug-15	MS	West Point	McCharen Field	5/3461	06/17/15	VOR/DME-B, Amdt 5

**EFFECTIVE 20 AUGUST 2015**

FDC **5/3461** M83 IAP MCCHAREN FIELD, WEST POINT, MS. VOR/DME-B,  
AMDT 5... CIRCLING CAT A MDA 920/HAA 715, CATS B/C MDA 940/HAA 735.  
DELETE GOLDEN TRIANGLE RGNL ALTIMETER SETTING MINIMUMS.  
CHANGE ALTIMETER SETTING NOTE TO READ: USE GOLDEN TRIANGLE  
RGNL ALTIMETER SETTING, WHEN NOT RECEIVED, USE COLUMBUS AFB  
ALTIMETER SETTING. CHART NOTE: HELICOPTER VISIBILITY REDUCTION  
BELOW 1 SM NOT AUTHORIZED. THIS IS VOR/DME-B, AMDT 5A.  
1504281831-PERM