

U.S. Department  
of Transportation

800 Independence Ave., S.W.  
Washington, D.C. 20591

**Federal Aviation  
Administration**

**Transmittal Letter 15-16**

**June 19, 2015**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows: .....EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
23-Jul-15	MO	Caruthersville	Caruthersville Memorial	5/4043	6/9/2015	RNAV (GPS) RWY 36, Amdt 1

**FDC 5/4043** M05 IAP CARUTHERSVILLE MEMORIAL, CARUTHERSVILLE, MO.  
RNAV (GPS) RWY 36, AMDT 1... CHANGE NOTE: VISIBILITY REDUCTION BY  
HELICOPTER NA, TO READ: HELICOPTER VISIBILITY REDUCTION BELOW 1  
SM NOT AUTHORIZED. CHART NOTE: PROCEDURE NA AT NIGHT.

**THIS IS RNAV (GPS) RWY 36, AMDT 1A. 1506051523-PERM**