

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows: .....EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
8-Dec-98	NC	Washington	Warren Field	8/8350	011/09/98	LOC RWY 5, Amdt 1

**FDC 8/8350** FI/P WARREN FIELDS, WASHINGTON, NC LOC RWY 5, AMDT 1...  
DELETE NOTE: "OBTAIN LOCAL ALTIMETER SETTING ON CTAF; IF NOT  
RECEIVED, USE NEW BERN ALTIMETER SETTING". DELETE: NEW BERN  
ALTIMETER SETTING MINIMUMS.

**THIS IS LOC RWY 5, AMDT 1A.**