

**Federal Aviation
Administration**

Transmittal Letter 15-21

August 28, 2015

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DAT	SUBJECT
15-Oct-15	VA	Richmond	Richmond Executive- Chesterfield County	5/0092	08/06/15	ILS OR LOC RWY 33, Amdt 2C

AIRAC Date: 15 October 2015

FDC **5/0092** FCI IAP RICHMOND EXECUTIVE-CHESTERFIELD COUNTY,
RICHMOND, VA. ILS OR LOC RWY 33, AMDT 2C... CIRCLING CAT C MDA 760/HAA
524. DELETE NOTE: FOR INOPERATIVE MALSR, INCREASE S-LOC 33 CATS C-D
VISIBILITY TO 1 3/8 MILE.. THIS IS ILS OR LOC RWY 33, AMDT 2D. 1505121312-
PERM