

**Federal Aviation
Administration**

Transmittal Letter 08-08

MARCH 7, 2008

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DAT	SUBJECT
02/28/08	ND	FARGO	HECTOR INTL	8/6453		ILS OR LOC RWY 18, ORIG

AIRAC Date: 28 FEBRUARY 2008

FDC 8/6453 FAR FltP HECTOR INTL, FARGO, ND. ILS OR LOC RWY 18, ORIG ... CHART NOTE: VIS CAT AIBICID R VR 1800 AUTHORIZED WITH THE USE OF FD OR AP OR HUD TO DA. ADD ATTENTION SYMBOL TO MAKE NOTE APPLY TO S-ILS 18 LINE OF MINIMUMS. THIS IS ILS OR LOC RWY 18, ORIG-A.