

**Federal Aviation
Administration**

Transmittal Letter 15-23

September 25, 2015

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DAT	SUBJECT
12-Nov-15	ND	Fargo	Hector Intl	5/4367	09/08/15	VOR OR TACAN RWY 36, Orig-B

AIRAC Date: 12 November 2015

FDC **5/4367** FAR IAP HECTOR INTL, FARGO, ND. VOR OR TACAN RWY 36, ORIG-B... CIRCLING CATS D/E MDA 1620/HAA 719, VIS CAT D 2 1/4, CAT E 2 1/2. STABS FIX MINIMUMS: CIRCLING CAT C MDA 1520/HAA 619, VIS 1 3/4, CATS D/E MDA 1620/HAA 719, VIS CAT D 2 1/4, CAT E 2 1/2, ALTERNATE MINIMUMS STANDARD, EXCEPT CAT D 800-2 1/4, CAT E 800-2 1/2. THIS IS VOR OR TACAN RWY 36 ORIG-C. 1509022021-PERM