

**Federal Aviation
Administration**

Transmittal Letter 02-16

JULY 05, 2002

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DAT	SUBJECT
06/24/02	TX	Madisonville	Madisonville	2/6015		VOR/DME RWY 18, AMDT 2

AIRAC Date: 24 JUNE 2002

FDC 2/6015/51RIFIIP MADISONVILLE MUNI, MADISONVILLE, TX. VOR/DME RWY 18, AMDT 2 ... CHANGE MAPT TO: LEONA (LOA) VORTAC R-167.98/12.41 DME. TIIIS IS VOR/DME RWY 18, AMDT 2A.