

U.S. Department
of Transportation

800 Independence Ave., S.W.
Washington, D.C. 20591

**Federal Aviation
Administration**

Transmittal Letter 15-26

November 26, 2015

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME,
LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
10-Dec-15	CA	Bishop	Bishop	5/2713	10/23/15	LDA/DME RWY 16, Orig-A

EFFECTIVE 10 DECEMBER 2015

**FDC 5/2713 BIH IAP EASTERN SIERRA RGNL, BISHOP, CA. LDA/DME RWY
16, ORIG-A... CHANGE AIRPORT NAME FROM EASTERN SIERRA RGNL TO
BISHOP. THIS IS LDA/DME RWY 16 ORIG-B. 1509171730-PERM**