

U.S. Department
of Transportation

800 Independence Ave., S.W.
Washington, D.C. 20591

**Federal Aviation
Administration**

Transmittal Letter 15-26

November 26, 2015

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME,
LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
10-Dec-15	CA	Bishop	Bishop	5/2729	10/23/15	Takeoff Minimums and (Obstacle) DP, Amdt 3

EFFECTIVE 10 DECEMBER 2015

FDC 5/2729 BIH ODP EASTERN SIERRA RGNL, BISHOP, CA. TAKEOFF
MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES AMDT 3...
CHANGE AIRPORT NAME FROM EASTERN SIERRA RGNL TO BISHOP. THIS
IS TAKEOFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES,
AMDT 3A. 1509171730-PERM