

U.S. Department
of Transportation

800 Independence Ave., S.W.
Washington, D.C. 20591

**Federal Aviation
Administration**

Transmittal Letter 16-03

December 18, 2015

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
4-Feb-16	NY	New York	John F Kennedy Intl	5/7063	12/07/15	ILS OR LOC RWY 4L, Amdt 11

AIRAC Date: 4 February 2016

FDC 5/7063 JFK IAP JOHN F KENNEDY INTL, NEW YORK, . ILS OR LOC RWY 4L, AMDT 11... DELETE NOTE: LOC PROCEDURE NA DURING SIMULTANEOUS OPERATIONS.

THIS IS ILS OR LOC RWY 4L, AMDT 11A. 1510151116-PERM