

**Federal Aviation
Administration**

Transmittal Letter 16-10

March 25, 2016

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC,
LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS,
MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs,
Identified as follows:EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
28-Apr-16	IN	Richmond	Richmond Muni	5/7977	03/09/16	VOR RWY 6, Amdt 12

AIRAC Date: 28 APRIL 2016

FDC 5/7977 RID IAP RICHMOND MUNI, RICHMOND, IN. VOR RWY 6, AMDT
12... S-6 HAT 524 ALL CATS. BOTKE FIX MINIMUMS: S-6 HAT 364 ALL CATS.
CHART NOTE: HELICOPTER VISIBILITY REDUCTION BELOW 3/4 SM NOT
AUTHORIZED. CHART TDZE 1136. THIS IS VOR RWY 6, AMDT 12A.
1511041626-PERM