

**Federal Aviation
Administration**

Transmittal Letter 16-15

June 3, 2016

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DAT	SUBJECT
21-Jul-16	TX	Houston	George Bush Intercontinental/ Houston	6/9022	5/12/16	ILS OR LOC RWY 9, ILS RWY 9 (SA CAT I), ILS RWY 9 (SA CAT II), Amdt 10

AIRAC Date: 21 JULY 2016

FDC 6/9022 IAH IAP GEORGE BUSH INTERCONTINENTAL/HOUSTON, HOUSTON, TX. ILS OR LOC RWY 9, AMDT 10 ... ILS RWY 9 (SA CAT I & II), AMDT 10 ... DELETE THRE 91. CHART TDZE 91. THIS IS ILS OR LOC RWY 9, AMDT 10A, ILS RWY 9 (SA CAT I & II), AMDT 10A. 1603232128-PERM