

**Federal Aviation
Administration**

Transmittal Letter 16-18

July 15, 2016

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DAT	SUBJECT
18-Aug-16	OH	Akron	Akron Fulton Intl	6/1392	7/7/16	NDB RWY 25, Amdt 14

AIRAC Date: 18 AUGUST 2016

FDC 6/1392 AKR IAP AKRON FULTON INTL, AKRON, OH. NDB RWY 25, AMDT 14...
DELETE THRE 1059. CHART TDZE 1059. THIS IS NDB RWY 25, AMDT 14A. 1603291917-
PERM