

**Federal Aviation
Administration**

Transmittal Letter 18-03

December 15, 2017

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
1-Feb-18	AK	Palmer	Palmer Muni	7/2504	12/4/17	Takeoff Minimums and Obstacle DP, Amdt 2

AIRAC Date: 1 FEBRUARY 2018

FDC **7/2504** PAQ ODP PALMER MUNI, Palmer, AK. TAKEOFF MINIMUMS AND
(OBSTACLE) DEPARTURE PROCEDURES AMDT 2... CHANGE AIRPORT NAME
FROM PALMER MUNI TO PALMER BUDDY WOODS MUNI. ALL OTHER DATA
REMAINS AS PUBLISHED. THIS IS TAKEOFF MINIMUMS AND (OBSTACLE)
DEPARTURE PROCEDURES, AMDT 2A. 1710121131-PERM