

**Federal Aviation  
Administration**

**Transmittal Letter 18-07**

**February 9, 2018**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,  
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,  
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:  
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBE	FDC DATE	SUBJECT
29-Mar-18	SC	Columbia	Columbia Metropolitan	7/0591	1/25/18	RNAV (GPS) RWY 5, Amdt 2B

**AIRAC Date: 29 MARCH 2018**

FDC **7/0591** CAE IAP COLUMBIA METROPOLITAN, Columbia, SC. RNAV (GPS) RWY 5, AMDT 2B... CHART PLANVIEW NOTE: PROCEDURE NA FOR ARRIVALS AT LEDAS ON V155 SOUTHWEST BOUND, AND ON V311 NORTHWEST BOUND. DELETE PLANVIEW NOTE: PROCEDURE NA FOR ARRIVALS AT LEDAS ON V311 NORTHWEST BOUND. CHART PLANVIEW NOTE: PROCEDURE NA FOR ARRIVALS AT ADCOM ON V53 SOUTHEAST BOUND. DELETE PLANVIEW NOTE: PROCEDURE NA FOR ARRIVALS AT ADCOM ON V54 SOUTHEAST BOUND. THIS IS RNAV (GPS) RWY 5, AMDT 2C. 1712071309-PERM