

**Federal Aviation
Administration**

Transmittal Letter 10-24

October 15, 2010

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

18-Nov-10	TX	Longview	East Texas Rgnl	0/7564	10/5/10	ILS OR LOC RWY 13, AMDT 13
-----------	----	----------	-----------------	--------	---------	-------------------------------

AIRAC Date: 18 NOVEMBER 2010

FDC 0/7564 GGG FI/P EAST TEXAS RGNL, LONGVIEW, TX. ILS OR LOC RWY 13,
AMDT 13... CHANGE LR-295 TO LR-299. CHANGE LR-319 TO LR-322. THIS IS ILS OR
LOC RWY 13, AMDT 13A.