

**Federal Aviation  
Administration**

**Transmittal Letter 18-12**

**April 20, 2018**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,  
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,  
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:  
.....EFFECTIVE UPON PUBLICATION

| AIRA<br>C | STATE | CITY  | AIRPORT    | FDC<br>NUMB | FDC<br>DATE | SUBJECT                       |
|-----------|-------|-------|------------|-------------|-------------|-------------------------------|
| 24-May-18 | SD    | Huron | Huron Rgnl | 8/7325      | 4/11/18     | LOC/DME BC RWY 30,<br>Amdt 13 |

**AIRAC Date: 24 MAY 2018**

FDC **8/7325** HON IAP HURON RGNL, Huron, SD. LOC/DME BC RWY 30, AMDT 13...  
CHART NOTE: CIRCLING RWY 17, 35 NA AT NIGHT. DELETE NOTE: DME  
REQUIRED. EQUIPMENT REQUIREMENTS NOTE: DME REQUIRED. THIS IS  
LOC/DME BC RWY 30, AMDT 13A. 1804111508-PERM