

**Federal Aviation
Administration**

Transmittal Letter 17-18

July 14, 2017

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
17-Aug-17	LA	Shreveport	Shreveport Rgnl	7/2751	7/7/17	RNAV (GPS) RWY 24, AMDT 2

AIRAC Date: 17 AUGUST 2017

FDC **7/2751** SHV IAP SHREVEPORT RGNL, Shreveport, LA. RNAV (GPS) RWY 24, AMDT 2... DELETE NOTE: VGSI AND RNAV GLIDEPATH NOT COINCIDENT (VGSI ANGLE 3.00/TCH 61). DELETE PLANVIEW NOTE: PROCEDURE NA FOR ARRIVAL ON EIC VORTAC AIRWAY RADIALS 092 CW 199. CHART PLANVIEW NOTE: PROCEDURE NA FOR ARRIVAL ON EIC VORTAC AIRWAY RADIALS 092 CW 239. THIS IS RNAV (GPS) RWY 24, AMDT 2A. 1706151157-PERM