

**Federal Aviation  
Administration**

**Transmittal Letter 02-22**

**September 27, 2002**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,  
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,  
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:  
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBE	FDC DATE	SUBJECT
31-Oct-02	NJ	Teterboro	Teterboro	2/8518	8/15/02	VOR RWY 24, ORIG

**AIRAC Date: 31 October 2002**

FDC 2/8518 /TEB/ FI/P TETERBORO, TETERBORO, NJ. VOR RWY 24,  
ORIG....CHANGE PLANVIEW NOTE TO READ: ADF AND DME AND RADAR  
REQUIRED. TIDS IS VOR RWY 24, ORIG-A.