

**Federal Aviation
Administration**

Transmittal Letter 08-15

JUNE 13, 2008

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DAT	SUBJECT
5/31/08	TX	Madisonville	Madisonville	8/9636		RNAV (GPS) RWY 18, ORIG

AIRAC Date: 31 MAY 2008

FDC 8/9636 51R FI/P MADISONVILLE MUNI, MADISONVILLE, TX. RNAV (GPS) RWY 18, ORIG. DELETE NOTE: GPS OR RNP-0.3 REQUIRED. MISSED APPROACH: CLIMB TO 1500, THEN CLIMBING RIGHT TURN TO 2100 DIRECT LOA VORTAC AND HOLD. THIS IS RNAV (GPS) RWY 18, ORIG-A.