

**Federal Aviation  
Administration**

**Transmittal Letter 22-22**

**September 2, 2022**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,  
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,  
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:  
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
10/6/2022	NY	Albany	Albany Intl	2/3102	8/15/2022	VOR RWY 28, Orig- E

**AIRAC Date: 6 OCTOBER 2022**

FDC 2/3102 ALB IAP ALBANY INTL, ALBANY, NY. VOR RWY 28, ORIG-E... CIRCLING CAT C MDA 860/HAA 575. CHANGE NOTE TO READ: STRAIGHT IN RWY 28 NA AT NIGHT, CIRCLING RWY 10, 28 NA AT NIGHT. THIS IS VOR RWY 28, ORIG-F. 2206231512-PERM