

**Federal Aviation
Administration**

Transmittal Letter 22-02

November 26, 2021

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
12/30/2021	KS	Wichita	Wichita Dwight D Eisenhower	1/5763	11/9/2021	ILS OR LOC RWY 19R, Amdt 5G

AIRAC Date: 30 DECEMBER 2021

FDC 1/5763 ICT IAP WICHITA DWIGHT D EISENHOWER NTL, WICHITA, KS. ILS OR LOC RWY 19R, AMDT 5G... CIRCLING CAT C/D MDA 1980/HAA 647, VIS CAT C 1 3/4. SPOIL FIX MINIMUMS: CIRCLING CAT C/D MDA 1980/HAA 647, VIS CAT C 1 3/4. THIS IS ILS OR LOC RWY 19R, AMDT 5H. 2109101409-PERM