

**Federal Aviation
Administration**

Transmittal Letter 23-13

April 28, 2023

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
6/15/2023	AK	King Salmon	King Salmon	3/5870	4/6/2023	VOR Y OR TACAN Y RWY 30, Amdt 12

AIRAC Date: 15 JUNE 2023

FDC 3/5870 AKN IAP KING SALMON, KING SALMON, AK. VOR Y OR TACAN Y RWY 30,
AMDT 12... DELETE CHART FAS OBST: 179 TREE 593941N/1563311W. CHART FAST OBST:
179 TREE 583945N/1563317W. THIS IS VOR Y OR TACAN Y RWY 30, AMDT 12A.
2304041457-PERM