

**Federal Aviation
Administration**

Transmittal Letter 21-13

April 30, 2021

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
6/17/2021	MD	Baltimore	Martin State	1/4587	2/25/2021	VOR OR TACAN RWY 15, Orig-C

AIRAC Date: 17 JUNE 2021

FDC 1/4587 MTN IAP MARTIN STATE, BALTIMORE, MD. VOR OR TACAN RWY 15, ORIG-C...
CHART NOTE: CIRCLING NA NORTHEAST OF RWY 15-33. THIS IS VOR OR TACAN RWY
15, ORIG-D. 2102171548-PERM