

**Federal Aviation
Administration**

Transmittal Letter 22-04

December 24, 2021

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
1/27/2022	AR	Batesville	Batesville Rgnl	1/0564	12/13/2021	LOC RWY 8, Amdt 1B

AIRAC Date: 27 JANUARY 2022

FDC 1/0564 BVX IAP BATESVILLE RGNL, BATESVILLE, AR. LOC RWY 8, AMDT 1B... CUCAL FIX MINIMUMS:
CIRCLING CAT B MDA 1000/HAA 535, CAT C MDA 1220/HAA 755, CAT D MDA 1400/HAA 935; VIS CAT C 2
1/4, CAT D 3. THIS IS LOC RWY 8, AMDT 1C. 2111011406-PERM