

U.S. Department
of Transportation

800 Independence Ave., S.W.
Washington, D.C. 20591

**Federal Aviation
Administration**

Transmittal Letter 15-16

June 19, 2015

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
23-Jul-15	MO	Caruthersville	Caruthersville Memorial	5/4038	6/9/2015	VOR/DME RWY 18, Orig

FDC 5/4038 M05 IAP CARUTHERSVILLE MEMORIAL, CARUTHERSVILLE, MO.
VOR/DME RWY 18, ORIG... CHANGE NOTE: VISIBILITY REDUCTION BY
HELICOPTER NA, TO READ: HELICOPTER VISIBILITY REDUCTION BELOW 1
SM NOT AUTHORIZED. CHART NOTE: PROCEDURE NA AT NIGHT.

THIS IS VOR/DME RWY 18 ORIG-A. 1506051518-PERM