

**Federal Aviation
Administration**

Transmittal Letter 20-16

June 12, 2020

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
7/16/2020	NC	Statesville	Statesville Rgnl	0/5727	6/3/2020	RNAV (GPS) RWY 10, Amdt 1A

AIRAC Date: 16 JULY 2020

FDC 0/5727 SVH IAP STATESVILLE RGNL, STATESVILLE, NC. RNAV (GPS) RWY 10, AMDT 1A... CHART
NOTE: VGSI AND RNAV GLIDEPATH NOT COINCIDENT (VGSI ANGLE 3.00/TCH 50.3). THIS IS RNAV
(GPS) RWY 10, AMDT 1B. 2006031415-PERM