

**Federal Aviation
Administration**

Transmittal Letter 21-20

August 6, 2021

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
9/9/2021	LA	Sulphur	Southland Fld	1/2685	7/21/2021	LOC RWY 15, Amdt 2

AIRAC Date: 9 SEPTEMBER 2021

FDC 1/2685 UXL IAP SOUTHLAND FLD, SULPHUR, LA. LOC RWY 15, AMDT 2... CIRCLING CAT C MDA 680/HAA 670, CAT D MDA 680/HAA 670, CAT C VIS 1 3/4. WEDIT FIX MINIMUMS CIRCLING CAT C MDA 680/HAA 670, CAT D MDA 680/HAA 670, CAT C VIS 1 3/4. CHANGE NOTE TO READ: WHEN LOCAL ALTIMETER SETTING NOT RECEIVED, USE LAKE CHARLES RGNL ALTIMETER SETTING AND INCREASE ALL MDA 20 FEET AND CIRCLING VISIBILITY CAT C/D 1/4 SM. THIS IS LOC RWY 15, AMDT 2A. 2107201902-PERM