

**Federal Aviation  
Administration**

**Transmittal Letter 17-18**

**July 14, 2017**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows: .....EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
17-Aug-17	ND	Bismarck	Bismarck Muni	7/0710	7/5/17	RNAV (GPS) RWY 31, Amdt 1A

**AIRAC Date: 17 AUGUST 2017**

FDC **7/0710** BIS IAP BISMARCK MUNI, Bismarck, ND. RNAV (GPS) RWY 31, AMDT 1A... CHART NOTE: ASTERISK, ASTERISK CHART NOTE: RVR 1800 AUTHORIZED WITH USE OF FD OR AP OR HUD TO DA.. THIS IS RNAV (GPS) RWY 31, AMDT 1B. 1706271707-PERM