

**Federal Aviation
Administration**

Transmittal Letter 22-18

August 11, 2022

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
8/11/2022	CO	Denver	Colorado Air And Space Port	2/7610	7/5/2022	Takeoff Minimums and Obstacle DP, Amdt 3A

AIRAC Date: 11 AUGUST 2022

FDC 2/7610 CFO ODP COLORADO AIR AND SPACE PORT, DENVER, CO. TAKEOFF MINIMUMS AND
(OBSTACLE) DEPARTURE PROCEDURES AMDT 3A... CHANGE TAKEOFF OBSTACLE NOTES RWY 28 TO
READ: RWY 26. ALL OTHER DATA REMAINS AS PUBLISHED. THIS IS TAKEOFF MINIMUMS AND
(OBSTACLE) DEPARTURE PROCEDURES, AMDT 3B. 2207051511-PERM