



## Federal Aviation Administration

---

# SAFETY ALERT

Date: June 23, 2016

To: Users of:

U.S. Terminal Procedures Publication (TPP), SC-5 Volume  
digital-Terminal Procedures Publication (d-TPP)

From: Aeronautical Information Services

Subject: TPP SC-5 volume not updated for RNAV (GPS) RWY 16 for Liberty Muni (T78)  
Liberty, TX

---

In the Terminal Procedure Publication, SC-5 volume, and the digital-Terminal Procedures Publication, effective June 23, 2016, for Liberty Muni (T78) Liberty, TX, RNAV (GPS) RWY 16 was not updated. The changes in PNOTAM FDC 5/8015 were not applied to the chart. The corrected chart will be published on July 21, 2016.


Attached is the correct file for the SC-5 volume RNAV (GPS) RWY 16 for Liberty Muni (T78) Liberty, TX.

RNAV (GPS) RWY 16  
LIBERTY MUNI (T78)


MISSED APPROACH: Climb to 3000  
direct WOVOL and hold.

CTAF  
122.9 **L**

## RADAR REQUIRED



3000	WOVOL
------	-------



CATEGORY	A	B	C	D
LP MDA	620-1	550 (600-1)	NA	
LNAV MDA	640-1	570 (600-1)	NA	
CIRCLING	640-1	570 (600-1)	NA	

