



## Federal Aviation Administration

---

# SAFETY ALERT

Date: July 7, 2016

To: Users of:  
U.S. Terminal Procedures Publication (TPP)  
digital-Terminal Procedures Publication (d-TPP)

From: Aeronautical Information Services

Subject: TAKEOFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES for  
Everett-Stewart Rgnl (UCY) Union City, TN not displayed in d-TPP and missing  
from SE-1 TPP index

---

In the digital-Terminal Procedures Publication, effective July 21, 2016, for Everett-Stewart Rgnl (UCY) Union City, TN, TAKEOFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES is showing a 'D' flag when the procedure is still active. The TAKEOFF MINIMUMS is also missing from the index of the Terminal Procedure Publication, SE-1 volume. The correction will be published in the digital-Terminal Procedures Publication on August 18, 2016 and in the Terminal Procedure Publication, SE-1 volume on September 15, 2016.

The 'D' flag in the digital-Terminal Procedures Publication will not allow the Takeoff Minimums to be displayed. The current TAKEOFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES, AMDT 1 for UCY can be found at <http://aeronav.faa.gov/d-tpp/1608/SE1TO.PDF> on page L20.