



Federal Aviation Administration

SAFETY ALERT


Date: July 17, 2016

To: Users of the U.S Terminal Procedure Publication (TPP) Southwest (SW)
Volume 4 of 4, and digital-TPP (d-TPP)


From: Aeronautical Information Services

Subject: Falcon Field, Mesa, AZ (FFZ) – Missing Taxiway A

Taxiway A connecting the approach end of Runway 04L and the approach end of 04R is missing from the Falcon Field, Mesa, Arizona (FFZ) Airport Diagram in the **U.S. Terminal Procedures Publication (TPP) Southwest (SW) Volume 4 of 4, and the *digital* –TPP (*d*-TPP) Volume 1608**. Taxiway A was reconfigured and should appear is shown below.



Attached is the corrected chart for the SW-4 volume Airport Diagram for Falcon Field (FFZ), Mesa, AZ.



SW-4, 21 JUL 2016 to 15 SEP 2016

SW-4, 21 JUL 2016 to 15 SEP 2016