

ROLLN ONE ARRIVAL (RNAV)

CLEVELAND, OHIO

CLEVELAND APP CON
124.0 354.025
CLEVELAND-HOPKINS INTL D-ATIS
127.85
BURKE LAKEFRONT ATIS
125.25

CLEVELAND-HOPKINS
INTL

BURKE LAKEFRONT

WILLOUGHBY LOST NATION MUNI

CUYAHOGA COUNTY

CLAPT
7000 210K

SWEEEE
7000 210K

LORAIN COUNTY RGNL

GROHL
6000 210K

MEEAT (10)

HENDX
9000

KCLE Ldg Rwy 6L/R

NIXXS
6000

Ldg KBKL, KCGF, KLNN, KLPR

LVISS
9000
8000

STOHN
14000
9000

ROLLN
17000
11000

GEDDY
FL230 280K
17000

JPLIN

JANYS

- NOTE: RADAR required.
- NOTE: RNAV 1.
- NOTE: DME/DME/IRU or GPS required.
- NOTE: Jet aircraft expect "DESCEND VIA" clearance from Cleveland Center.
- NOTE: Jet aircraft descend via Mach number until intercepting 280K. Maintain 280K until slowed by the STAR.
- NOTE: CLE landing South: Use Rwy 24R transition, expect runway assignment prior to ROLLN.
- NOTE: CLE landing North: Use Rwy 6L transition, expect runway assignment prior to ROLLN.

NOTE: Chart not to scale.

ARRIVAL ROUTE DESCRIPTION

JANYS TRANSITION (JANYS.ROLLN1)

- KCLE: From ROLLN on track 010° to cross STOHN between 9000 and 14000.
- LANDING KCLE RWY 6L/R: From STOHN on track 312° to cross LVISS between 8000 and 9000, then on track 312° to cross NIXXS at 6000, then on track 312° to cross GROHL at 6000 and at 210K, then on heading 236° or as assigned by ATC. Expect RADAR vectors to final approach course.
- LANDING KCLE RWY 24L/R: From STOHN on track 010° to MEEAT, then on track 010° to cross CLAPT at 7000 and at 210K, then on heading 056° or as assigned by ATC. Expect RADAR vectors to final approach course.
- LANDING KCLE RWY 28: From STOHN on track 018° to cross SWEEEE at 7000 and at 210K, then on heading 101° or as assigned by ATC. Expect RADAR vectors to final approach course.
- LANDING KBKL/KLNN/KCGF/KLPR: From ROLLN on track 010° to cross STOHN between 9000 and 14000, then on track 034° to cross HENDX at 9000, then on track 034°. Expect RADAR vectors to final approach course.

ROLLN ONE ARRIVAL (RNAV)

CLEVELAND, OHIO