


LOC/DME I-CMH 111.75 Chan 54 (Y)	APP CRS 281°	Rwy Ldg TDZE 815 Apt Elev 815
--	------------------------	---


ILS or LOC RWY 28L
JOHN GLENN COLUMBUS INTL (CMH)

ADF required. DME or RADAR required.	MALSR	MISSED APPROACH: Climb to 1400 then climbing left turn to 3000 direct BU LOM and hold.
Simultaneous approach authorized.		
For inop ALS, increase S-LOC 28L Cat C/D visibility to 1½ SM.		

D-ATIS 124.6	COLUMBUS APP CON 125.95 371.975	COLUMBUS TOWER 132.7 257.8	GND CON 121.9 348.6	CLNC DEL 126.3	CPDLC
------------------------	---	--------------------------------------	-------------------------------	--------------------------	-------



ELEV 815	D	TDZE 815
-----------------	----------	-----------------



TDZ/CL Rwy 10R-28L HIRL Rws 10R-28L and 10L-28R
FAF to MAP 4.5 NM
Knots 60 90 120 150 180
Min:Sec 4:30 3:00 2:15 1:48 1:30